



INJECTION GATE POSITION SHOULD BE DISCUSSED WITH BOSCH ENGINEERING;
AND THE BURR BE LESS THAN 0.1MM WHEN INJECTION GATE CUTTED OFF;

[illegible]